



P.O. Box 538
East Granby, CT 06026

Ph: (860) 844-0101

<http://www.wildlifecontrolsupplies.com/>


Product Overview – [Cinch Mole Trap](#)

A-Forward Set Wire

B-Rear Set Wire

C-Trigger Wire

D-Active Jaw Wire



HOW TO SET A [CINCH TRAP](#)

Step 1: Hold the trap so the set wires A & B are hanging loose. Pull the trigger wire C back as show in the illustration, the trap is now ready to be set.

Step 2: Holding the trap firm with one hand, raise the active jaw wire D and lower it to the opposite side of the trap base. Position the forward set wire across the active jaw wire as shown.

Step 3: Position the rear set wire B across set wire A. Push the trigger wire C forward making sure the set wire B is positioned behind the tab as illustrated. When you push the trigger wire C make sure you are in the guide area on the rear of the trap base.

Step 4: The trap is now set and ready to be positioned into the mole run.

Cinch Trap Placement: Dig away dirt on top of mole's mound to expose hole. Insert the trap into the hole as shown in step 4 above, making sure that the jaws of the trap fit snug against the wall of the hole by twisting back and forth. Leave the hole open to encourage the mole to investigate the change in the tunnel system. The mole comes between the jaws and activates the trigger mechanism and the powerful steel spring closes the jaws shut around the moles middle with instantaneous effectiveness. Remove the trap, release and dispose of the carcass. Check area for other activity and set as necessary.